

vebro

Medium duty PU concrete with UV resistant, gloss or satin sealer for industrial applications.

## why choose **vebro**crete Industrial?

IJ

Temperature resistance up to 70°C



Excellent resistance to corrosive agents & aggressive cleaning solvents



Excellent cleanability & seamless hygienic finish



Excellent UV stability

Slate Grey (RAL 7015)	Dusty Grey (RAL 7037)	Traffic Grey A (RAL 7042)
1200		
Green	Blue	Red
Yellow		

## system design & typical properties

1 Primer	<b>vebro</b> crete PU MF (pf) (unpigmented)	1.90 kg/m <sup>2</sup>
2 Body Coat	vebrocrete PU MF (pf)	5.70 kg/m <sup>2</sup>
3 Coating	vebro PU UV Seal (Gloss) or vebro PU UV Seal (Satin)	1st coat: 0.12 kg/m <sup>2</sup> 2nd coat: 0.12 kg/m <sup>2</sup>

Thickness	4.0 mm
FeRFA Type BS 8204-6	Туре 7
Temperature Resistance	0 – 70°C
Fire Resistance EN 1350-1	B <sub>ff</sub> S1
Co-efficient of Thermal Expansion ASTM C531	5.8 × 10 <sup>-5</sup> / °C
Slip Resistance TRLL Pendulum Slip Test / DIN 51130	Dry >70, Wet >21 / R9
Abrasion Resistance EN 13892-4 / BS 8204-2	AR 0.5 / Special Class
Shore D Hardness	80 after 28 days
Compressive Strength EN 196-1 / ASTM C109	50 N/mm²
Speed of Cure (at 20°C)	Light Foot Traffic – 12 hours Full Chemical Cure – 7 days

For a full technical profile, please refer to the data sheet for each product in the system design.

## contact the **vebro** team

w: vebropolymers.com | e: australia@vebropolymers.com | t: 1800 727 865\*

22/09/25. Please note, the applied colours may differ from the examples shown. vebrocrete systems may exhibit a yellowing effect over time resulting from thermal, UV or chemical exposure. This will be more pronounced on light grey or blue shades, "Colours marked with an asterisk will incur an additional supplement. The typical physical properties given above are derived from testing in a controlled laboratory environment at 20°C. Results derived from testing field applied samples may vary dependent upon site conditions. The slip resistance figures given above are affected by application techniques and prevailing site conditions. Slip resistance can reduce over time due to poor maintenance, general wear or surface contaminants. Good housekeeping practices should be observed.







